



Article number:WD-5800 1CE

Specifications

Power source.	AC mains (supplied AC adapter must be used)
Input / Output	2 antenna inputs, 8 antenna outputs, 4 DC power outputs for receivers
Band-pass frequency	VHF and UHF range
Gain	0 dB
Distribution output	Antenna A x4, Antenna B x4
Power source.	AC mains (supplied AC adapter must be used)
Finish.	Steel, Aluminium,
Operating humidity.	30 to 85% RH (no condensation)
Operating temperature.	-10 to +50 C°



WD-5800

Appearance